

# General Environmental Incident Summary

**Incident:** 2127      **Date/Time Notice:** 12/2/2013      **DEM Incident No:**  
**Responsible Party:** Travis Leach  
**Date Incident:** 12/1/2013      **Time Incident:** 0800      **Duration:** 1 hours  
**County:** McKenzie      **Twp:** 149      **Rng:** 94      **Sec:** 22      **Qtr:**  
**Lat:** 47.71266      **Long:** -102.70670      **Method:** Interpolation from map  
**Location Description:** Highway 22. Half-mile north of Sage Springs

**Submitted By:** Curtis Hanzel      **Affiliation:** FBS Safety  
**Address:** PO Box 516  
**City:** Killdeer      **State:** ND      **Zip:** 58640

## **Received By:**

### **Contact Person:**

PO Box 295  
Halliday, ND 58636

## **Distance Nearest Occupied Building:**

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** Production Salt Water

**Volume Spilled:** 35.00 barrels      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## **Cause of Incident:**

Truck hauling salt water to disposal rolled spilling approximately 35 barrels of salt water

## **Risk Evaluation:**

**# of Fatalities:**      **# of Injuries:** 1      **Affected Medium:** 03 - soil

## **Potential Environmental Impacts:**

## **Action Taken or Planned:**

Standing water was sucked up and hauled away.

**Wastes Disposal Location:** Jessica Disposal

## **Agencies Involved:**

## **Updates**

---

**Date:** 12/2/2013    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

Incident has impacted areas off of location. Follow-up necessary.

---

**Date:** 12/4/2013    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

Arrived on location 12/4/13 at 12:15 p.m. CT. Phoned an FBS representative and secured the correct site coordinates. Observed site and took photographs. The area was snow- and ice-covered with no evidence of salt water in the ditch area along Highway 22. There was a front-end loader and scraper on the site in an area where tire ruts showed a vehicle had entered the off-ramp area on the east side of the highway. Tire ruts were approximately 2 to 3 feet in depth and approximately 40 feet in length from the edge of the road. Spoke with the management of FBS and was informed that Bemis Construction was on site to excavate any soil and transport to the Kildeer landfill. He also mentioned that they had a vac truck at the scene shortly after the accident and had pumped out most of the saltwater from the truck before it reached the ditch. He added that Bemis Construction had done the road work this past summer, and they felt it would be best if they did the repair work. FBS representative will follow up with a phone call after reclamation of the area is complete.

---

**Date:** 8/11/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

I arrived at the site at 14:05 p.m. The weather was sunny, 86°F, with the wind from the southeast 10-15 mph. The vegetation in the ditch has come back. No further followup needed at this time.